

Dri-Eaz Technical Bulletin

Burlington, Wash. - June 21, 2016

Important action recommended for Dri-Eaz dehumidifiers with removable power cords - Models F410, F411, F412, F413 and F532

Always remove the power cord from dehumidifiers by grasping the IEC plug as shown in the "Correct" photos below. Removing the cord by pulling on the power cord as shown in the photos labeled "incorrect," will damage the plug and/or the IEC receptacle. The damage may cause a poor connection between the plug and receptacle, possibly leading to failure at the point of connection.

Inspect the IEC plug and IEC receptacle for damage due to incorrect power cord removal. If the IEC plug does not fit securely into the IEC receptacle, the cord must be replaced immediately.

IMPORTANT: Damage to IEC receptacle or dehumidifier resulting from improper removal of the power cord is not covered by warranty. The IEC power cord is a wear item and is not covered by warranty.

CORRECT PLUG REMOVAL Models F412 & F532 Grasp IEC plug and pull straight out



CORRECT PLUG REMOVAL Models F410 & F411 Grasp IEC plug and pull straight out



INCORRECT PLUG REMOVAL Models F410 & F411 Models F412 & F532



Follow these simple instructions to prolong the life of the cord and ensure reliable performance of your dehumidifiers from one job to the next. Failure to follow these instructions will result in equipment downtime and repair/replacement costs of the power cord, IEC receptacle and/or the dehumidifier's electrical control system.

Replacement part numbers: Power cord – 02-01614 IEC Receptacle – 02-01616

Check out all of the Legend Brands product offerings

Dri-Eaz Chemspec ProRestore Sapphire Scientific VersaClean Systems

Copyright© 2015 Legend Brands, All rights reserved. We want to make sure you see information on Legend Brands and its related brands (Chemspec, Dri-Eaz Products, ProRestore and Sapphire Scientific) Our mailing address is: LegendBrands | 15180 Josh Wilson Road, Burlington, WA 98233