

Troubleshooting Guide

VersaCarpet™ VC700 Carpet and Upholstery Cleaner

LEGEND BRANDS, INC.
 15180 Josh Wilson Road ▪ Burlington, WA 98233
 800-932-3030 ▪ <http://VersaCleanSystems.com>

PROBLEM	SOLUTION
APO slow or not working	<ol style="list-style-type: none"> 1. Verify shut off valve is open on QD 2. Clean APO filter 3. Check for excessive build up of sand and sludge in waste tank/clean out if necessary 4. Possible impeller damage/check and replace if necessary
No water flow to cleaning head	<ol style="list-style-type: none"> 1. Verify water is turned on at water source 2. Verify shut off valve at QD is open 3. Remove vacuum intake cap and assure water injection tube is inserted into center of cleaning head
Weak vacuum/over wet carpet	<ol style="list-style-type: none"> 1. Check waste tank filter for blockage/Clean if necessary 2. Check vacuum intake for blockage/clean if necessary 3. Check vacuum shoes(5) for clogging/clean if necessary 4. Possible foam build up in waste tank/apply Crystal defoamer to carpet
Waste tank vacuum float ball cutting off vacuum	<ol style="list-style-type: none"> 1. Waste tank is full/verify APO system is working properly 2. Foam build up in waste tank/use Crystal defoamer
<p><i>If the problem you are experiencing is not listed here, call your local distributor or contact our Service Department toll-free at 800-932-3030 for further assistance.</i></p>	

VISIT WWW.VERSACLEANSYSTEMS.COM